Square Root of (N) Sampling Plans:

Procedures and Tables for Inspection of Quality Attributes

Lynn Torbeck and Joyce Torbeck

www.pda.org/bookstore

CONTENTS

Preface
Acknowledgements
Introduction
Caution for Correct Use

1 FDA REGULATORY REQUIREMENTS FOR SAMPLING AND SAMPLING PLANS

2 INTRODUCTION TO ATTRIBUTE SAMPLING PLANS

3 REPRESENTATIVE SAMPLING

4 THE THREE SQRT (N) PLANS

5 USING THE TABLES

6 TABLE OF AQL AND UQL FOR n = 0.4 SQRT (N)

www.pda.org/bookstore

7 TABLE FOR AQL AND UQL FOR n = 1+ SQRT (N)

8 TABLE FOR ASQ AND UQL FOR n = FOR 1.5 SQRT (N)

9 STATISTICAL INTERPRETATION OF THE TABLES

10 THE SOURCE OF SQUARE ROOT OF (N) PLANS

11 COMPARISON OF SQRT (N) PLANS TO ANSI/ASQ Z1.4

12 CAN AQL = 0.0?

13 ATTRIBUTE SAMPLING PLAN DOCUMENTATION

14 GLOSSARY AND TERMINOLOGY

15 REFERENCES

16 INTERNET REFERENCES

Index

www.pda.org/bookstore